

Installation example: Nozzle-side installation

Technical information

The gate insert is screwed into the nozzle side of the mould. The front of the gate insert is sealed off by the cavity.

- to reduce pressure loss.
- to minimize shear.

